





FIG. 3









10 DEG BLADE HIGH ADHESION
0 DEG BLADE
UNCREPED TAD -10 DEG BLADE LOW ADHESION -UNPRESSED HANDSHEET -8 - DRY-CREPE CONTROL 15 DEG BLADE -2 -63 PRESSURE DROP, INCHES H<sub>2</sub>0 **E** 400+ <del>-</del>002 <del>1</del>009 1600-1400-1200-

3





FIG.














FIG. 9











FIG. 10B



















lookesla olosoe





















FIG. 17

194

182

186

186

198

198


198


190


170

170

180











FIG. 21


190

224
224
224
224



FIG. 22












3 338 FIG. 24 3
















FIG. 28 TYPICAL PRESSURE ROLL CURVE




FIG. 29






FIG. 30





FIG. 31

SHOE PRESS WITH LARGE DIAMETER TRANSFER CYLINDER AND WITH FELT PARTIALLY WRAPPING CYLINDER







SHOE PRESS TAPERED ON THE EXIT SIDE SO THAT BLANKET/FELT CAN BE RAPIDLY REMOVED FROM SHEET







FIG. 33

SHOE PRESS TAPERED ON THE EXIT SIDE SO THAT FELT CAN BE RAPIDLY REMOVED FROM THE SHEET WHILE THE BLANKET IS SIMULTANEOUSLY RAPIDLY REMOVED FROM THE FELT










FIG. 35A

